

INDEX TO PHOTOGRAPHS

Pit 4 Diversion Dam
Pit River West of State Highway 89
Big Bend Vicinity
Shasta County
California

HAER No. CA-317

David G. De Vries, photographer

June 2001

- CA-317-1 VIEW TO THE NORTHEAST TOWARD THE DOWNSTREAM,
SOUTHWEST SIDE OF THE DAM.
- CA-317-2 LOOKING DOWNRIVER TOWARD THE DAM. THE TUNNEL
INTAKE BUILDING IS VISIBLE AT THE RIGHT.
- CA-317-3 CENTER SECTION OF TRUSS FOOT BRIDGE AND
PERSPECTIVE OF THE THREE STRUCTURAL PIERS. VIEW TO
SOUTHEAST.
- CA-317-4 SLAB AND BUTTRESS SECTION, OBLIQUE, LOOKING SOUTH.
PART ONE OF A TWO PART PANORAMA.
- CA-317-5 DRUM GATES WITH THE FOOT BRIDGE ABOVE. PART TWO OF
A TWO PART PANORAMA.
- CA-317-6 LOOKING SOUTH ALONG THE NORTHWEST BANK TOWARD
CONCRETE PARAPET, FROM THE TUNNEL INTAKE BUILDING.
- CA-317-7 LOOKING WEST, DOWNSTREAM, OVER THE TRAINING WALL.
- CA-317-8 TRUSS FOOT BRIDGE, LOOKING EAST. THE DRUM GATES
AND SPILLWAYS ARE IN THE FOREGROUND.

INDEX TO PHOTOGRAPHS

Pit 4 Diversion Dam
 Pit River West of State Highway 89
 Big Bend Vicinity
 Shasta County
 California

HAER No. CA-317

David G. De Vries, photographer

June 2001

- CA-317-1 VIEW TO THE NORTHEAST TOWARD THE DOWNSTREAM,
 SOUTHWEST SIDE OF THE DAM.

- CA-317-2 LOOKING DOWNRIVER TOWARD THE DAM. THE TUNNEL
 INTAKE BUILDING IS VISIBLE AT THE RIGHT.

- CA-317-3 CENTER SECTION OF TRUSS FOOT BRIDGE AND
 PERSPECTIVE OF THE THREE STRUCTURAL PIERS. VIEW TO
 SOUTHEAST.

- CA-317-4 SLAB AND BUTTRESS SECTION, OBLIQUE, LOOKING SOUTH.
 PART ONE OF A TWO PART PANORAMA.

- CA-317-5 DRUM GATES WITH THE FOOT BRIDGE ABOVE. PART TWO OF
 A TWO PART PANORAMA.

- CA-317-6 LOOKING SOUTH ALONG THE NORTHWEST BANK TOWARD
 CONCRETE PARAPET, FROM THE TUNNEL INTAKE BUILDING.

- CA-317-7 LOOKING WEST, DOWNSTREAM, OVER THE TRAINING WALL.

- CA-317-8 TRUSS FOOT BRIDGE, LOOKING EAST. THE DRUM GATES
 AND SPILLWAYS ARE IN THE FOREGROUND.

PI 4 DIVERSION DAM
HAER No. CA-317
INDEX TO PHOTOGRAPHS (page 2)

- CA-317-9 VIEW TO SOUTHEAST ACROSS THE TOP OF THE DAM,
SHOWING CIRCULAR STAIR HOUSE. STAIRS LEAD DOWN TO
THE GATE OPERATING GALLERY.
- CA-317-10 TRUSS FOOT BRIDGE, LOOKING TOWARD EAST RIVER BANK.
STAIR HOUSE IS TO RIGHT OF WALKWAY.
- CA-317-11 A VIEW TO THE NORTHWEST ALONG THE FOUR FOOT WIDE
WALKWAY ATOP THE SLAB AND BUTTRESS SECTION. FROM
LEFT TO RIGHT, THE FLOAT HOUSE, STAIR HOUSE, AND
THE TUNNEL INTAKE BUILDING ARE VISIBLE.
- CA-317-12 STAIR HOUSE, LOOKING TO NORTHWEST.
- CA-317-13 DETAIL, CONTROL WHEELS FOR THE DRUM GATE TRASH
RACKS, LOOKING NORTHEAST FROM THE CENTER PIER.
- CA-317-14 LOOKING NORTHWEST THROUGH WOODS TOWARD THE SLAB
AND BUTTRESS SECTION. NEW DAM MODIFICATIONS WILL
IMPACT THIS AREA.
- CA-317-15 SOUTH SIDE OF DAM SHOWING BAFFLE PIERS AT FOOT OF
SPILLWAY TO LEFT AND PARTIAL VIEW OF BUTTRESSES
AND SIDEWALLS TO RIGHT.
- CA-317-16 EAST ELEVATION OF FLOAT HOUSE AND FISH WATER
RELEASE OUTLET. PART OF ENERGY DISSIPATING BAFFLE
PIER SYSTEM IS VISIBLE AT LEFT.
- CA-317-17 VIEW TO NORTH SHOWING FISH WATER RELEASE OUTLET AS
WELL AS SOUTHWEST AND SOUTHEAST ELEVATIONS OF
FLOAT HOUSE.
- CA-317-18 VIEW TO NORTHEAST FROM BELOW, SHOWING BAFFLE
PIERS, SPILLWAYS, AND DRUM GATES.

PI 4 DIVERSION DAM
HAER No. CA-317
INDEX TO PHOTOGRAPHS (page 2)

- CA-317-9 VIEW TO SOUTHEAST ACROSS THE TOP OF THE DAM,
SHOWING CIRCULAR STAIR HOUSE. STAIRS LEAD DOWN TO
THE GATE OPERATING GALLERY.
- CA-317-10 TRUSS FOOT BRIDGE, LOOKING TOWARD EAST RIVER BANK.
STAIR HOUSE IS TO RIGHT OF WALKWAY.
- CA-317-11 A VIEW TO THE NORTHWEST ALONG THE FOUR FOOT WIDE
WALKWAY ATOP THE SLAB AND BUTTRESS SECTION. FROM
LEFT TO RIGHT, THE FLOAT HOUSE, STAIR HOUSE, AND
THE TUNNEL INTAKE BUILDING ARE VISIBLE.
- CA-317-12 STAIR HOUSE, LOOKING TO NORTHWEST.
- CA-317-13 DETAIL, CONTROL WHEELS FOR THE DRUM GATE TRASH
RACKS, LOOKING NORTHEAST FROM THE CENTER PIER.
- CA-317-14 LOOKING NORTHWEST THROUGH WOODS TOWARD THE SLAB
AND BUTTRESS SECTION. NEW DAM MODIFICATIONS WILL
IMPACT THIS AREA.
- CA-317-15 SOUTH SIDE OF DAM SHOWING BAFFLE PIERS AT FOOT OF
SPILLWAY TO LEFT AND PARTIAL VIEW OF BUTTRESSES
AND SIDEWALLS TO RIGHT.
- CA-317-16 EAST ELEVATION OF FLOAT HOUSE AND FISH WATER
RELEASE OUTLET. PART OF ENERGY DISSIPATING BAFFLE
PIER SYSTEM IS VISIBLE AT LEFT.
- CA-317-17 VIEW TO NORTH SHOWING FISH WATER RELEASE OUTLET AS
WELL AS SOUTHWEST AND SOUTHEAST ELEVATIONS OF
FLOAT HOUSE.
- CA-317-18 VIEW TO NORTHEAST FROM BELOW, SHOWING BAFFLE
PIERS, SPILLWAYS, AND DRUM GATES.

PIT 4 DIVERSION DAM
HAER No. CA-317
INDEX TO PHOTOGRAPHS (page 3)

CA-317-19 TRAINING WALL, AND NORTHWESTERN BAYS OF THE SLAB
AND BUTTRESS SECTION.

CA-317-20 LOOKING DOWNSTREAM AT BAFFLE PIERS AND THE
TRAINING WALL.

CA-317-21 SOUTHEAST SPILLWAY, TO EAST.

CA-317-22 NORTHWEST SPILLWAY, WITH FISH WATER RELEASE OUTLET
PIPE IN FOREGROUND AT LEFT.

CA-317-23 VIEW TO NORTH OF SLAB AND BUTTRESS SECTION OF DAM,
NEAR CENTER OF THE SOUTH SIDE.

CA-317-24 OBLIQUE VIEW OF BAYS ALONG SLAB AND BUTTRESS
SECTION OF DAM. VIEW TO EAST.

CA-317-25 LOOKING INSIDE THE TALLEST, MOST NORTHWESTERN BAY
OF THE SLAB AND BUTTRESS SECTION. TRAINING WALL
AT LEFT.

CA-317-26 SOUTH END OF TRAINING WALL, LOOKING DOWNSTREAM.

CA-317-27 CORRIDOR ALONG GATE OPERATING GALLERY, LOOKING TO
THE NORTHWEST. LADDERS LEAD TO OPERATOR'S DECK.

CA-317-28 DRUM GATE DRAIN VALVES AT NORTHWEST END OF
GALLERY.

CA-317-29 CENTER PIER IN GATE OPERATING GALLERY. VIEW TO
SOUTHEAST.

CA-317-30 NORTHWEST AND SOUTHWEST ELEVATIONS OF TUNNEL
INTAKE BUILDING, LOOKING UPSTREAM TO EAST-
NORTHEAST.

PIT 4 DIVERSION DAM
HAER No. CA-317
INDEX TO PHOTOGRAPHS (page 3)

CA-317-19 TRAINING WALL, AND NORTHWESTERN BAYS OF THE SLAB
AND BUTTRESS SECTION.

CA-317-20 LOOKING DOWNSTREAM AT BAFFLE PIERS AND THE
TRAINING WALL.

CA-317-21 SOUTHEAST SPILLWAY, TO EAST.

CA-317-22 NORTHWEST SPILLWAY, WITH FISH WATER RELEASE OUTLET
PIPE IN FOREGROUND AT LEFT.

CA-317-23 VIEW TO NORTH OF SLAB AND BUTTRESS SECTION OF DAM,
NEAR CENTER OF THE SOUTH SIDE.

CA-317-24 OBLIQUE VIEW OF BAYS ALONG SLAB AND BUTTRESS
SECTION OF DAM. VIEW TO EAST.

CA-317-25 LOOKING INSIDE THE TALLEST, MOST NORTHWESTERN BAY
OF THE SLAB AND BUTTRESS SECTION. TRAINING WALL
AT LEFT.

CA-317-26 SOUTH END OF TRAINING WALL, LOOKING DOWNSTREAM.

CA-317-27 CORRIDOR ALONG GATE OPERATING GALLERY, LOOKING TO
THE NORTHWEST. LADDERS LEAD TO OPERATOR'S DECK.

CA-317-28 DRUM GATE DRAIN VALVES AT NORTHWEST END OF
GALLERY.

CA-317-29 CENTER PIER IN GATE OPERATING GALLERY. VIEW TO
SOUTHEAST.

CA-317-30 NORTHWEST AND SOUTHWEST ELEVATIONS OF TUNNEL
INTAKE BUILDING, LOOKING UPSTREAM TO EAST-
NORTHEAST.

PIT 4 DIVERSION DAM
HAER No. CA-317
INDEX TO PHOTOGRAPHS (page 4)

- CA-317-31 LOOKING NORTH AT THE SOUTHWEST AND SOUTHEAST
ELEVATIONS OF THE TUNNEL INTAKE STRUCTURE. THE
TRASH RACK DEBRIS LOADER AND CLEANER IS AT THE
RIGHT OF THE INTAKE STRUCTURE.
- CA-317-32 NORTHEAST ELEVATION OF TUNNEL INTAKE BUILDING FROM
THE ACCESS ROAD.
- CA-317-33 GATE CABLES AND PULLEYS FOR TUNNEL INTAKE GATE
INSIDE THE TUNNEL INTAKE BUILDING.
- CA-317-34 INTERIOR UPPER DECK OF TUNNEL INTAKE BUILDING,
LOOKING SOUTH AT THE GATE WINCH.

PIT 4 DIVERSION DAM
HAER No. CA-317
INDEX TO PHOTOGRAPHS (page 4)

- CA-317-31 LOOKING NORTH AT THE SOUTHWEST AND SOUTHEAST
ELEVATIONS OF THE TUNNEL INTAKE STRUCTURE. THE
TRASH RACK DEBRIS LOADER AND CLEANER IS AT THE
RIGHT OF THE INTAKE STRUCTURE.
- CA-317-32 NORTHEAST ELEVATION OF TUNNEL INTAKE BUILDING FROM
THE ACCESS ROAD.
- CA-317-33 GATE CABLES AND PULLEYS FOR TUNNEL INTAKE GATE
INSIDE THE TUNNEL INTAKE BUILDING.
- CA-317-34 INTERIOR UPPER DECK OF TUNNEL INTAKE BUILDING,
LOOKING SOUTH AT THE GATE WINCH.